









Hardware List

A	B	C	D	E	F
					
X4	X2	X6	X1	X2	X1


STEP1:



STEP2:



STEP3:



All Type "A" Screws Finger Tight Plus One Turn

STEP4:



STEP5:

