



MV 2251

< EXPLODE VIEW >


< 2 SPEED TRANSFORMATION >



REPLACE



(INCLUDED)



NOT INCLUDE

WASHER 8x12x0.2

F/H SCREW 3x8M

2 SPEED GEAR 45T
(MV0451)

2 SPEED CLUTCH HOUSING

2 SPEED ONE WAY MOUNT W/B.B.

2 SPEED GEAR 50T (MV0501)

NOT INCLUDE

B.B. 8x12x3.5T

2 SPEED CLUTCH
(MV3333)

WASHER 8x12x0.2

F/H SCREW 3x8M

CLUTCH BELL W/O PINION GEAR

PINION GEAR 19T (A)

PINION GEAR 14T (B)

WASHER 3x4.8x0.2 OR 5x8x0.4

B.B. 5x8x2.5

CAP SCREW 3x6M

MAIN GAER SHAFT

WASHER 5x8x0.4

B.B. 5x10x4

ENGINE

PINION GEAR	ITEM NO	TEETH
(A)	MV3201	20T
(B)	MV3151	15T
(A)	MV3211	21T
(B)	MV3161	16T





NOVEMBER, 2004




RASP

Z

ATTENTION : WITHOUT THIS MARK
PLEASE RASP AWAY
THE SECTION AREA .



Z



*UNIT : mm

JUNE,2004